

Drymec

Replacement oil water separator service kits

Drymec	Enviro EW18		
	DS 100	DS 300	
	DS 750	DS 1500	
Jorc (CP)	CT 3	CT 7	
	CT 15		
	Puro mini (035)	Puro	
	Puro midi	Puro Grand	
	Extender	Sepremium 2	
	Sepremium 5 (050)	Sepremium 10 (100)	
	Sepremium 20 (200)	Sepremium 30 (300)	
Sepura	120 ST	360 ST	
	900 ST	1800 ST	
Denco	RCE 200	RCE 400	
	RCE 1000	O rings available	
Ultrafilter	UFS 7.5 plus	UFS 5 S plus	
		UFS 7.5 S plus	
		UFS 10 S plus	10N
	UFS 15 plus	UFS 15 S plus	15N
	UFS 30 plus	UFS 30 S plus	30N
	UFS 60 plus	UFS 60 S plus	60N
	UFS 120 plus	UFS 120 S plus	
	UFS 240 plus	UFS 240 S plus	
Beko	Owamat 1	Owamat 2	Owamat 10
	Owamat 3	Owamat 4	Owamat 11
	Owamat 5R	Owamat 6 TS 16	
	Owamat 8	Owamat 20	
	KT03	KT 05	IR
Zander – water	WT 1/WT 10	S 1	ECS 6
	WT 2	S 2 S3 S4 S8 S15	ECS 12
	WT 3	S 30	ECS 18
	WT 20	SL 60	ECS 24
	WT 30	Air bag	ECS 30
	SL 1 – SL 8	SL 30	ECS 36
	SL 15	SL 60	ECS 42
Domnick Hunter	DH 2010	ES 2200 /ES 90	
	DH 2015 SLB1	ES 2300 / ES 125	
	DH 2030 SLB 2	ES 2400 / ES 250	
	ES 2100 / ES 36	ES 2500 / ES 500	
	ES 2150	ES 2600 / ES 1000	
	ESMK 1	ESMK 2	
	ESMK 3 SLB 3		



HSMK		HSMK	
Hankison	1	HS 60 - 70 - 120	
	2	HS 140 180 240 300 480	
	3	HS 900	
Atlas Copco		OSW 5 & OSW 11	
		OSW 30	
		OSW 55	
Atlas Copco Including Mark & Worthington		OSC 35	
		OSC 95	
		OSC 145	
		OSC 355	
Sterling		CSR 150	
		CSR 450	
		CSR 1000	
HiLine		GEN 2 mini	
		GEN 2 +	
		Consep 100	
		Consep 900	

NOTE

Manufacturers data is for reference only.

Service kits sold by Drymec Ltd are not original manufacturers product

DRYMEC Ltd.
Unit 4R Bramhall Moor Technology Park
Pepper Road
Hazel Grove
Stockport SK7 5BW

Drymec

OMI Electron	25	
	50	
	90	
	180	
	300	
	600	
Wortmann	1	DSP
	2	90
	3	150
	8	210

HSMK

HS 1800	4
HS 3600	5

Air bags

OSW 110
OSW 315

OSC 600
OSC 825
OSC 1200
OSC 2400



GEN 2
GEN 2 tandem
Consep 300

Tel 0161 487 4747
Fax 0161 487 3778
www.drymec.com
sales@drymec.com